

# Abstract

A method for producing a phosphor having a high brightness is described. The method for producing a phosphor having a high brightness, comprises steps of:

- 5       contacting a luminescent material containing Si and/or Ge with an acid,  
          separating solid from the acid, and  
          drying an obtained solid.